



oznaka	$\varnothing d$ (mm)	L (mm)	A (mm)	B (mm)	C (mm)	K ₁ (mm)	D (mm)	E (mm)	F (mm)	K ₂ (mm)
600009	25	1500	M16x1.5	20	60	6x6x55				
600010	30	1500	M20x1.5	22	75	8x7x70				
600011	35	1500	M24x2	24	80	10x8x74				
600012	40	1500	M24x2	27	95	12x8x90				
600013	45	1500	M33x2	30	100	14x9x95				
600014	50	1500	M36x3	30	105	14x9x100				
600066	25	1500	M16x1.5	20	60	6x6x55	45	25	M16x1.5	8x7x40
600067	30	1500	M20x1.5	22	75	8x7x70	45	25	M20x1.5	8x7x40
600068	35	1500	M24x2	24	80	10x8x74	55	30	M24x2	10x8x50
600069	40	1500	M24x2	27	95	12x8x90	55	30	M24x2	12x8x50
600070	45	1500	M33x2	30	100	14x9x95	70	35	M30x2	14x9x65
600071	50	1500	M36x3	30	105	14x9x100	70	35	M36x3	14x9x65

